For More Questions *Click Here*

1. When filing soft metals, the file teeth are clogged with minute particles of metal. The file should be cleaned by		
(A) Washing it with water (B) Rubbing on wood		
(C) Washing it with dilute acid		
(D) Using file card		
Answer: Option D		
2. The process used to improve fatigue resistance of the metal by setting up compressive stresses in its surface, is known as		
(A) Hot piercing		
(B) Extrusion		
(C) Cold peening		
(D) Cold heading		
3. Thermit welding is often used in		
(A) Replacing broken gear teeth		
(B) Repairing broken shears		
(C) Joining rails, truck frames and locomotive frames etc.		
C C		
(D) All of the above		
4. The electron beam welding can be carried out in		
C C C C C C C C C C C C C C C C C C C		
(A) Open air		
(B) A shielded gas environment (C) Vacuum		
(C) Vacuum		
(D) A pressurized inert gas chamber		
5. An oxidising process used for aluminium and magnesium articles is called		
(A) Galvanizing		
(B) Anodizing		
(C) Parkensing		
(D) Sherardizing		

6. The algebraic difference between the minimum limit and the basic size is called		
0	(A) Actual deviation	
0		
0	(B) Upper deviation	
	(C) Lower deviation	
0	(D) Fundamental deviation	
7. Piercing is an operation of cutting		
0	(A) A cylindrical hole in a sheet of metal by the punch and the die	
0	(B) A hole (other than cylindrical) in a sheet of metal by the punch and the die	
0		
0	(C) A flat sheet to the desired shape	
	(D) A number of holes evenly spaced in a regular pattern on a sheet of metal	
8. <mark>In _</mark>	welding, the weld may be made either from left to right or from right to left.	
O		
	(A) Forehand	
0	(B) Backhand	
0	(C) Vertical	
0		
	(D) None of these	
9. The	temperature of oxy-hydrogen flame is oxyacetylene flame.	
0		
	(A) Same as	
0	(B) Less than	
0	(C) More than	
0	(D) None of these	
	noving mandrel is used in	
0	(A) Wire drawing	
0	(B) Tube drawing	
0	(C) Metal cutting	
	(O) Inclui cutting	

